



experience the passion

23172 Alcalde Drive, Unit B
Laguna Hills, CA 92653
Phone: (949) 699-1059
Fax: (949) 699-1097

AirWild 33% Extra 330L Additional Items You May Need

Description	Qty.	Comment
AirWild Twist'd Servo Extensions, 36"	2	For elevator servos (use 36" + 12" to build up a 48" length, may vary)
AirWild Twist'd Servo Extensions, 12"	4	For elevator, aileron servos
AirWild Twist'd Servo Y-Connect, 10"	3	For aileron 2X, rudder servos 1X
AirWild Twist'd Servo Extensions, 6"	2	For aileron connections, from receiver
Cermark DSC Switches	3	2 for receiver batteries, 1 for ignition battery
AirWild 35% Pilot Figure	1	Optional
Smart-Fly Optical Kill Switch	1	Ignition Kill (STRONGLY RECOMMENDED FOR SAFETY)
Cermark NiMH 6V/1650mA	2	For Rx
Cermark NiMH 6V/2700mA	1	For Ignition
Smart-Fly BatShare	1	Allows you to use two batteries to drive one Rx w/o concern for bat. Failure 2X battery capacity + redundancy
CF Nomex Panel, 12"x12"	1	Optional. Used to build floor board for mounting of Rx etc.
AirWild Nova Spinner, 5"	1	
Hitec 5945 Hi-Torque Digital Servo	8	Aileron x 4, elevator x 2, rudder x 2
Hitec 5245 Digital Mini Servo	1	Throttle
AirWild MLP Servo Arm, 2.5"	2	For rudder pull-pull use (ganged servos, series configuration)
Hanger 9 Pro Links	4	For rudder pull-pull use (length may vary depending on your placement)
Hanger 9 1/4 HD Double Ball Link	2	For rudder pull-pull use (approximately 2"~2.5" length)
Dubro 1/4 HD Ball Link	2	For rudder pull-pull use (ganged servos, series configuration)
Dynamite Pro Filter	1	Fuel Filter
Engine, 100cc, Gasoline	1	DA100, 3W106 etc.
Propeller	1	NX 27x10 2-blade, NX 28x10 2-blade, NX 26x12 3-blade (check w/ engine guide)
AirWild WingPAK Pro-Series	1	Optional, for 35% size

1. This list contains items that we believe offering the highest quality and reliability for our particular application. Nevertheless please do not feel constrained to such selection as many other comparable options are available on the market.
2. AirWild Hobbies in no way warrants these products on behalf of the original manufacturers. All warranty related issue should be addressed with the